

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
OKLA,
21-FLINT.V,
1A-

Hildebrand's Mill (Beck's Mill)
Flint vicinity
Delaware County
Oklahoma

HABS No. OK-29

Documentation: 5 exterior photos (1979)
2 interior photos (1979)
9 data pages (1975)

Walter Smalling, Jr., Photographer October 1979

- OK-29-1 NORTH-NORTHEAST (FRONT) ELEVATION
- OK-29-2 SIDE VIEW OF MILL, FROM SOUTHEAST
- OK-29-3 VIEW OF SIDE ELEVATION, LOOKING SOUTHWEST
- OK-29-4 SAWING AREA ON GROUND LEVEL, EAST-SOUTHEAST ELEVATION
- OK-29-5 LINE SHAFTING MOUNTED UNDERNEATH MILL, GROUND LEVEL, SOUTH-SOUTHEAST END OF BUILDING
- OK-29-6 GRIST MILL STONES IN CENTER (VERTICAL STAND WITH HANDLE TO LEFT OF STONES ADJUSTS SPACE BETWEEN STONES, THUS CONTROLLING FINENESS OF FLOUR. STONE CRANE AT RIGHT USED TO LIFT STONES FOR DRESSING). OTHER EQUIPMENT NOT IDENTIFIED. NOTE STAIRS IN LEFT REAR.
- OK-29-7 STORAGE ROOM, SECOND FLOOR, LOOKING SOUTH-SOUTHEAST